



MIDDLE-BROOK REGIONAL HEALTH COMMISSION

111 Greenbrook Road
Green Brook, NJ 08812
(732) 968-5151
www.middlebrookhealth.org

Kevin G. Sumner, Health Officer/Director
e-mail: ksumner@middlebrookhealth.org

PARTICIPATING MUNICIPALITIES
BOROUGH OF BOUND BROOK
TOWNSHIP OF GREEN BROOK
BOROUGH OF SOUTH BOUND BROOK
BOROUGH OF WATCHUNG
TOWNSHIP OF WARREN

RECREATIONAL BATHING ESTABLISHMENT INSPECTION REPORT

Name of Establishment Majors and View

Address of Establishment Loeffler Pools - Pool Mgmt Co.

Mailing Address _____

Telephone Number 732 489-5606 Camiles Co

Type of Establishment

Outdoor Pool

Indoor Pool _____

Whirlpool/Hot Tub _____

Wading Pool

Lake _____

Weather Conditions ~~65°~~ 65° F

Number of Bathers Pre-op inspection

Comments A Check List was provided prior to inspection by Loeffler Pools

* Bushes near outdoor shower need to be trimmed

new is
* Dressing Room wall near shower is in dis-repair

Person Interviewed Camile Loeffler Title Owner/mgr

Inspector Robyn Key Date 5/25/22

Rating

Satisfactory

Conditional _____

Unsatisfactory _____

<u>Gas Chlorine Equipment</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Cylinders Stored Properly		
Electric Switched Located Outside		
Automatic Chlorine Leak Detector Installed		
Respirators Available		
SCBA Provided		
Scale for Weighing Cylinder Available		
Valve Protection Caps Available and Used		
Other		

<u>Lakes</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Swimming Area is Clean and Safe		
Bathing Beach Designated by Water Buoys		
Hours of Operation Posted		
Adult Supervisor is Available		
Lifeguard Present for Every 300' of Beach		
Adult Certified in CPR & First Aid Present		
Lifeguard Provided		
Lifeguard Identified		
Lifeguard Supplied with Whistle		
Lifeguard Not Distracted by Other Duties		
First Aid Kit Provided		
Spine Board with Straps Provided		
Rules Posted		
Telephone Provided		
Platforms Meet Standards 26-5.10		
18" Ring Buoy with 75' of Rope Provided		
600' of Rope with Quick Release Provided		
12' Reach Pole Provided if Docks Present		
12' Paddle Rescue Board Provided		

<u>Dressing and Sanitary Facilities</u>	<u>Satisfactory</u>		<u>Unsatisfactory</u>	
	<u>MENS</u>	<u>WOMENS</u>	<u>MENS</u>	<u>WOMENS</u>
Rooms Clean and Sanitary	✓	✓		
Showers Clean and Sanitary	✓	✓		
Toilet Tissue Provided	✓	✓		
Waste Baskets Provided	✓	✓		
Sanitary Napkin Dispensers Provided	NA	NA		
Soap Dispensers Provided	✓	✓		
Hand Towels Provided	✓	✓		
Unbreakable Mirrors Provided	✓	✓		
Rooms are Well Lighted	✓	✓		
Rooms are Well Drained	✓	✓		
Floors are Made of Slip Resistant Materials	✓	✓		

<u>Whirlpool/Hot Tub</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Continuous Disinfection Occurring		
One Handrail for Each 50' Provided		
Temperature $\leq 104^{\circ}$ F		
Audible Temperature Alarm Provided		
Automatic Safety Shut-Off Provided		
Thermometer Accessible to Public Provided		
Personnel Aware of Pump Shut-Off Procedures		
Adult Supervisor Present		
Adult Certified in CPR & First Aid Present		
Precaution Sign Posted		
Depth Markings Posted		
First Aid Kit Provided		
Clock Readable from Whirlpool/Hot Tub		
Drain Covers Present and in Good Condition		
Sides Clean		
Deck Clean		
Deck In Good Repair		
Trash Containers Provided and Maintained		

<u>Miscellaneous</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Water Tested for Chlorine and pH Every 2 Hours	Pre-op	
Bound Log of Water Test Results Kept	✓	
Chlorine and pH Test Kit Provided	✓	
Chemicals Properly Stored	✓	
Pump Room Clean and Orderly	✓	
Hair Strainers Clean	✓	
Appropriate Garbage Containers Provided	✓	
Rodent and Insect Control Measures Employed	✓	
Facility Emergency Plan Present	✓	
Recreational Equipment Inspected and Maintained Weekly	✓	

<u>Record Keeping</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Personnel Certifications	✓	
Water Analysis Reports	✓	
Sanitary Survey Reports	✓	
Daily Number of Bathers	✓	
Accident Reports	✓	
Playground Inspection Reports	N/A	
Death and/or Drowning Reports	✓	
Electrical Bonding and Grounding Certification	✓	
Water Quality Logs	✓	