



MIDDLE-BROOK
REGIONAL HEALTH COMMISSION

111 Greenbrook Road
Green Brook, NJ 08812
(732) 968-5151
www.middlebrookhealth.org

Kevin G. Sumner, Health Officer/Director
e-mail: ksumner@middlebrookhealth.org

PARTICIPATING MUNICIPALITIES
BOROUGH OF BOUND BROOK
TOWNSHIP OF GREEN BROOK
BOROUGH OF SOUTH BOUND BROOK
BOROUGH OF WATCHUNG
TOWNSHIP OF WARREN

RECREATIONAL BATHING ESTABLISHMENT INSPECTION REPORT

Name of Establishment The Pointe (Crystal Ridge)

Address of Establishment US Hwy 22 West

Mailing Address NJ Pool Mgt Oversees Pool

Telephone Number 973-570 5610

Type of Establishment

Outdoor Pool	<input checked="" type="checkbox"/>
Indoor Pool	<input type="checkbox"/>
Whirlpool/Hot Tub	<input type="checkbox"/>
Wading Pool	<input checked="" type="checkbox"/>
Lake	<input type="checkbox"/>

Weather Conditions 78° F

Number of Bathers 0

Comments Pool + wading pool have debris floating on top. Pool water is cloudy.
* No Diagram of bathing facility

Person Interviewed Chris McElwee Title Manager (Rep.)

Inspector Robyn Ky Date 6/10/22 RA 11:00 AM

Rating

Satisfactory	<input type="checkbox"/>
Conditional	<input type="checkbox"/>
Unsatisfactory	<input checked="" type="checkbox"/>

WATER QUALITY

<u>Chemical Quality</u>	<u>Free Chlorine</u>	<u>Combined Chlorine</u>	<u>pH</u>	<u>Other (Specify)</u>
Outdoor Pool	>10.		7.2.	
Wading Pool	2-3		7.4.	
Indoor Pool				
Whirlpool Hot-Tub				
Lake				

<u>Physical Quality</u>	<u>Clarity</u>	<u>Algae</u>	<u>Temperature</u>	<u>Other (Specify)</u>
Outdoor Pool	Cloudy			
Wading Pool	Cloudy			
Indoor Pool				
Whirlpool Hot-Tub				
Lake				

<u>Bacteriological Quality</u>	<u>Standard Plate Count</u>	<u>Coliforms</u>	<u>Ps. Aeruginosa</u>	<u>Other (Specify)</u>
Outdoor Pool				
Wading Pool				
Indoor Pool				
Whirlpool Hot-Tub				
Lake				

Disinfection

Chlorine (Solid) Chlorine (Liquid) Chlorine (Gas)

Bromine Other (Specify)

Proper Storage of Chemicals Is Occurring? YES NO

Water Analyzed Weekly by Certified Lab? YES NO

Name of Certified Laboratory Garden State Labs

* The Chlorine in the swimming pool is very high. It appears to be Bleaching out the test kit colors.

<u>Gas Chlorine Equipment</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Cylinders Stored Properly		
Electric Switched Located Outside		
Automatic Chlorine Leak Detector Installed		
Respirators Available		
SCBA Provided		
Scale for Weighing Cylinder Available		
Valve Protection Caps Available and Used		
Other		

<u>Lakes</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Swimming Area is Clean and Safe		
Bathing Beach Designated by Water Buoys		
Hours of Operation Posted		
Adult Supervisor is Available		
Lifeguard Present for Every 300' of Beach		
Adult Certified in CPR & First Aid Present		
Lifeguard Provided		
Lifeguard Identified		
Lifeguard Supplied with Whistle		
Lifeguard Not Distracted by Other Duties		
First Aid Kit Provided		
Spine Board with Straps Provided		
Rules Posted		
Telephone Provided		
Platforms Meet Standards 26-5.10		
18" Ring Buoy with 75' of Rope Provided		
600' of Rope with Quick Release Provided		
12' Reach Pole Provided if Docks Present		
12' Paddle Rescue Board Provided		

<u>Dressing and Sanitary Facilities</u>	<u>Satisfactory</u>		<u>Unsatisfactory</u>	
	MENS	WOMENS	MENS	WOMENS
Rooms Clean and Sanitary				
Showers Clean and Sanitary				
Toilet Tissue Provided				
Waste Baskets Provided				
Sanitary Napkin Dispensers Provided				
Soap Dispensers Provided				
Hand Towels Provided				
Unbreakable Mirrors Provided				
Rooms are Well Lighted				
Rooms are Well Drained				
Floors are Made of Slip Resistant Materials				

<u>Wading Pools</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Continuous Disinfection Occurring	✓	
Personnel Aware of Pump Shut-Off Procedures	✓	
Individuals Present When in Operation	N/A	pre-op
Maximum Depth is 24" (18" at Perimeter)		
Drain Covers Present and in Good Condition	✓	
Sides Clean		✓
Bottom Clean		✓
Deck Clean	✓	
Deck in Good Repair	✓	
Trash Containers Provided and Maintained	✓	

<u>Swimming Pool</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Drain Covers Present and in Good Condition	✓	
Sides Clean	✓	✓
Bottom Clean	✓	✓
Deck Clean	✓	
Skimmers Clean		✓
Deck In Good Repair	✓	
Equipment in Good Repair	✓	
Continuous Disinfection Occurring	✓	
Adult Certified in CPR & First Aid Present		pre-op
Lifeguard Provided		pre-op
Lifeguard Identified		
Lifeguard Supplied with Whistle		
Lifeguard Not Distracted by Other Duties		
Personnel Aware of Pump Shut-Off Procedures		
Adult Supervisor Present		
2 Assist Poles/Hooks Provided	✓	
2 Life-rings Provided	✓	
First Aid Kit Provided	✓	
Spine Board with Straps Provided	✓	
Rules Posted	✓	
Depth Markings Posted	✓	
Pool Meets Enclosure Requirements	✓	
Diving Board is Slip-Resistant	N/A	N/A
Trash Containers Provided and Maintained	✓	

<u>Whirlpool/Hot Tub</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Continuous Disinfection Occurring		
One Handrail for Each 50' Provided		
Temperature ≤ 104°F		
Audible Temperature Alarm Provided		
Automatic Safety Shut-Off Provided		
Thermometer Accessible to Public Provided		
Personnel Aware of Pump Shut-Off Procedures		
Adult Supervisor Present		
Adult Certified in CPR & First Aid Present		
Precaution Sign Posted		
Depth Markings Posted		
First Aid Kit Provided		
Clock Readable from Whirlpool/Hot Tub		
Drain Covers Present and in Good Condition		
Sides Clean		
Deck Clean		
Deck In Good Repair		
Trash Containers Provided and Maintained		

<u>Miscellaneous</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Water Tested for Chlorine and pH Every 2 Hours	✓	
Bound Log of Water Test Results Kept	✓	
Chlorine and pH Test Kit Provided	✓	
Chemicals Properly Stored		
Pump Room Clean and Orderly	✓	
Hair Strainers Clean	✓	
Appropriate Garbage Containers Provided	✓	
Rodent and Insect Control Measures Employed	✓	
Facility Emergency Plan Present	✓	
Recreational Equipment Inspected and Maintained Weekly	N/A	

<u>Record Keeping</u>	<u>Satisfactory</u>	<u>Unsatisfactory</u>
Personnel Certifications	✓	
Water Analysis Reports	✓	
Sanitary Survey Reports	✓	
Daily Number of Bathers	✓	
Accident Reports	✓	
Playground Inspection Reports	N/A	
Death and/or Drowning Reports	✓	
Electrical Bonding and Grounding Certification	✓	(5/24/22)
Water Quality Logs	✓	

Spot Check Form

<u>Sample Location</u>	<u>pH</u>	<u>Free Chlorine</u>	<u>Combined Chlorine</u>	<u>Other</u>

Bound Log Maintained Yes _____ No _____

Test Kit Available Yes _____ No _____

Facility Maintained Adequately Yes _____ No _____

Comments
