

MIDDLE-BROOK REGIONAL HEALTH COMMISSION

111 Greenbrook Road Green Brook, NJ 08812 (732) 968-5151 www.middlebrookhealth.org

Kevin G. Sumner, Health Officer/Director e-mail: ksummer@middlebrookhealth.org

PARTICIPATING MUNICIPALITIES

BOROUGH OF BOUND BROOK
TOWNSHIP OF GREEN BROOK
BOROUGH OF SOUTH BOUND BROOK
BOROUGH OF WATCHUNG
TOWNSHIP OF WARREN

RECREATIONAL BATHING ESTABLISHMENT INSPECTION REPORT

Name of Establishr	ment The pointe
Address of Establis	hment 1 Crystel Rdg OctoAtholy.
Mailing Address	Amorcan pool
Telephone Number	(732)512-1900'
Type of Establishme	ent Outdoor Pool
	Indoor Pool
	Whirlpool/Hot Tub
	Wading Pool
	Lake
Weather Conditions	75°F
Number of Bathers	
Comments	Deeds Emegery John Warranthy Distyran
	10. 00. 7
	Rybo, Seposson - 443-580-931
Person Interviewed	MOHT NOWELL Title & Life Grand
Inspector	Robynsky Date 6/24/21
Rating	Satisfactory 1
	Conditional
	Unsatisfactory

WATER QUALITY

Chemical Quality	Free Chlorine	Combined Chlorine	рH	Other (Specify)
Outdoor Pool	7.5	6	7.8	T/S
Wading Pool	10			14
Indoor Pool	1 3			
Whirlpool Hot-Tub				
Lake				

Physical Quality	Clarity	<u>Algae</u>	<u>Temperature</u>	Other (Specify)
Outdoor Pool				
Wading Pool				
Indoor Pool				
Whirlpool Hot-Tub				
Lake				

Bacteriological Quality	Standard Plate Count	<u>Coliforms</u>	Ps. Aeruginosa	Other (Specify)
Outdoor Pool				7
Wading Pool				
Indoor Pool				
Whirlpool Hot-Tub				
Lake				

Disinfection Chlorine (Solid) Chlori	ine (Liquid) Chlorine (Gas)
Bromine Other (Specif	
Proper Storage of Chemicals Is Occurring?	YES NO
Water Analyzed Weekly by Certified Lab?	YES NO
Name of Certified Laboratory	

Gas Chlorine Equipment	Satisfactory	Unsatisfactory
Cylinders Stored Properly		
Electric Switched Located Outside		
Automatic Chlorine Leak Detector Installed		
Respirators Available		
SCBA Provided		
Scale for Weighing Cylinder Available		
Valve Protection Caps Available and Used		
Other		
	<u> </u>	Œ

Lakes	Satisfactory	Unsatisfactory
Swimming Area is Clean and Safe		
Bathing Reach Designated by Water Buoys		
Hours of Operation Posted		
Adult Supervisor is Available		
Lifeguard Present for Every 300' of Beach		
Adult Certified in CPR & First Aid Present		
Lifeguard Provided		
Lifeguard Identified		
Lifeguard Supplied with Whistle		
Lifeguard Not Distracted by Other Duties		
First Aid Kit Provided		
Spine Board with Straps Provided		
Rules Posted		
Telephone Provided		
Platforms Meet Standards 26-5.10		
18" Ring Buoy with 75' of Rope Provided		
600' of Rope with Quick Release Provided		
12' Reach Pole Provided if Docks Present		
12' Paddle Rescue Board Provided		

Dressing and Sanitary Facilities	Satisfactory				Unsatisfactory	
Mayoring a simulatory and filtration as a supposed in management of the same and	MENS		WOMENS		MENS	WOMENS
Rooms Clean and Sanitary						
Showers Clean and Sanitary						
Toilet Tissue Provided						
Waste Baskets Provided						
Sanitary Napkin Dispensers Provided						
Soap Dispensers Provided						
Hand Towels Provided						
Unbreakable Mirrors Provided						
Rooms are Well Lighted						
Rooms are Well Drained						
Floors are Made of Slip Resistant Materials		1				

Wading Pools	Satisfactory	Unsatisfactory
Continuous Disinfection Occurring		
Personnel Aware of Pump Shut-Off Procedures		
Individuals Present When in Operation		
Maximum Depth is 24" (18" at Perimeter)		
Drain Covers Present and in Good Condition		
Sides Clean		
Bottom Clean		
Deck Clean		
Deck in Good Repair		
Trash Containers Provided and Maintained		

Swimming Pool	Satisfactory	Unsatisfactory
Drain Covers Present and in Good Condition	V	
Sides Clean	V	
Bottom Clean	1//	
Deck Clean	V	
Skimmers Clean (6 5)		
Deck In Good Repair	V	
Equipment in Good Repair	/	
Continuous Disinfection Occurring		
Adult Certified in CPR & First Aid Present		
Lifeguard Provided	·//	
Lifeguard Identified		
Lifeguard Supplied with Whistle	·V	
Lifeguard Not Distracted by Other Duties	1	
Personnel Aware of Pump Shut-Off Procedures		
Adult Supervisor Present		
2 Assist Poles/Hooks Provided	V	
2 Life-rings Provided		
First Aid Kit Provided		
Spine Board with Straps Provided		
Rules Posted		
Depth Markings Posted		
Pool Meets Enclosure Requirements $\eta / \uparrow \uparrow $		
Diving Board is Slip-Resistant		
Trash Containers Provided and Maintained		

Whirpool/Hot Tub	Satisfactory	Unsatisfactory
Continuous Disinfection Occurring		
One Handrail for Each 50' Provided		
Temperature ≤ 104° F		
Audible Temperature Alarm Provided		
Automatic Safety Shut-Off Provided		
Thermometer Accessible to Public Provided		
Personnel Aware of Pump Shut-Off Procedures		
Adult Supervisor Present		
Adult Certified in CPR & First Aid Present		
Precaution Sign Posted		
Depth Markings Posted		
First Aid Kit Provided		
Clock Readable from Whirlpool/Hot Tub		
Drain Covers Present and in Good Condition		
Sides Clean		
Deck Clean		
Deck In Good Repair		
Trash Containers Provided and Maintained		

Miscellaneous	Satisfactory	Unsatisfactory	
Water Tested for Chlorine and pH Every 2 Hours	1/		
Bound Log of Water Test Results Kept			
Chlorine and pH Test Kit Provided			
Chemicals Properly Stored			
Pump Room Clean and Orderly			
Hair Strainers Clean			
Appropriate Garbage Containers Provided			
Rodent and Insect Control Measures Employed			
Facility Emergency Plan Present NO Sight			
Recreational Equipment Inspected and	J' Emess	US DIDN'	
Maintained Weekly			

Record Keeping	Satisfactory	Unsatisfactory
Personnel Certifications		
Water Analysis Reports		
Sanitary Survey Reports		
Daily Number of Bathers		
Accident Reports		
Playground Inspection Reports		
Death and/or Drowning Reports		
Electrical Bonding and Grounding Certification		
Water Quality Logs		

Whirpool/Hot Tub	Satisfactory	Unsatisfactory
Continuous Disinfection Occurring		
One Handrail for Each 50' Provided		
Temperature ≤ 104° F		
Audible Temperature Alarm Provided		
Automatic Safety Shut-Off Provided		
Thermometer Accessible to Public Provided		
Personnel Aware of Pump Shut-Off Procedures		
Adult Supervisor Present		
Adult Certified in CPR & First Aid Present		
Precaution Sign Posted		
Depth Markings Posted		
First Aid Kit Provided		
Clock Readable from Whirlpool/Hot Tub		
Drain Covers Present and in Good Condition		
Sides Clean		
Deck Clean		
Deck In Good Repair		
Trash Containers Provided and Maintained		

Miscellaneous	Satisfactory	Unsatisfactory
Water Tested for Chlorine and pH Every 2 Hours		
Bound Log of Water Test Results Kept		
Chlorine and pH Test Kit Provided		
Chemicals Properly Stored		
Pump Room Clean and Orderly		
Hair Strainers Clean		
Appropriate Garbage Containers Provided		
Rodent and Insect Control Measures Employed		
Facility Emergency Plan Present NO Scalet 1	Asmn +	
Recreational Equipment Inspected and	J Emesse	Japan Da
Maintained Weekly		

Record Keeping	Satisfactory	Unsatisfactory
Personnel Certifications		
Water Analysis Reports		
Sanitary Survey Reports		
Daily Number of Bathers		
Accident Reports		
Playground Inspection Reports		
Death and/or Drowning Reports		
Electrical Bonding and Grounding Certification		
Water Quality Logs		